



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D3914-041
Job Sheet 171444



Part No: D3914-041

Job Qty: 1 ea

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 2/1/18

Job Tracking No:

Due Date: 2/23/18

Created By: Linda Lacelle

Type: SOLD

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		2/22/18	0.00	0.00	Start Up Large Fab-5		D.M.L 18-2-13
100	Large Fab	1 pcs		2/22/18	0.00	6.67	Large Fab 1		JS 18-2-13
110	QC	1 pcs		2/22/18	0.00	0.00	QC9		CPC
120	QC	1 pcs		2/22/18	0.00	0.00	QC5		CPC
130	Powdercoat	1 pcs		2/22/18	0.00	0.40	Powdercoat4		BR 18-2-14
135	QC	1 pcs		2/22/18	0.00	0.00	QC3		JS 18-2-14
140	HandFinish	1 pcs		2/23/18	0.00	0.80	HandFinish3		JS 18-2-14
150	QC	1 pcs		2/23/18	0.00	0.00	QC3		JS 18-2-15
160	Packaging	1 pcs		2/23/18	0.00	0.00	Packaging3-2		JS 18-2-15
170	QC21-SA	1 Ea		2/23/18	0.00	0.00	QC21		21 FEB 15 2018

Part Op 100 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld hinge (3) and Mounting brackets as per dwg
Descriptions: D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***Cut out mesh where
label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label
plate before tacking mesh***

130 - *** mask sides of hinge prior to powdercoat***

140 - 1- Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- Install label as per dwg ***Mask
label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label ***

M 138700 START: 11:45. OUT: 3:30 FINISH: 12:15

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 Ea (2 ea)	90-Start up Operation	5033599
D3914-1	Rib	2 Ea (2 ea)	90-Start up Operation	5034699
D3914-7	Rib	2 Ea (2 ea)	90-Start up Operation	5032208
D4016-3	Hinge Half, Lid	3 Ea (3 ea)	90-Start up Operation	5032793
D4018-5	Rib	9 Ea (9 ea)	90-Start up Operation	5037656
D4020-5	Mesh (350 Basket Long, Lid)	1 Ea (1 ea)	90-Start up Operation	5032738 502997
D4021-3	Data Plate	1 Ea (1 ea)	90-Start up Operation	5032438
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 Ea (2 ea)	90-Start up Operation	5041480
D2728-3	Dart Logo Label Large	1 (1 ea)	140-HandFinish	N/A

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____		DISPOSITION		AGAINST DEPARTMENT/PROCESS																																																																																									
Part No. _____		Start up Operation 02/13/18 Job No: 171444		<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:33%;">Cross tube ☐</td> <td style="width:33%;">Water Jet ☐</td> <td style="width:33%;">Engineering ☐</td> </tr> <tr> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>		Cross tube ☐	Water Jet ☐	Engineering ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Composite ☐	Supplier ☐																																																																													
Cross tube ☐	Water Jet ☐			Engineering ☐																																																																																									
Small Fab ☐	Prod. Eng. Coord. ☐			Quality ☐																																																																																									
Finishing ☐	Rec/Store/Packaging ☐	Other ☐																																																																																											
Composite ☐	Supplier ☐																																																																																												
NCR No. _____		MRB (QS1042) Approval																																																																																											
Date : _____		Disposition		Completed By																																																																																									
Master Unit 000586 Job No 171444 Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K64 1K7 CANADA TEL: 1 613 632 - 5200 Email: sales@dartaero.com www.dartaerospace.com		Long Basket Lid Assembly (350)		Lead hand / Supervisor Approval Verification																																																																																									
				QC / QA Coordinator Approval																																																																																									
				ILT CATEGORY																																																																																									
<table style="width:100%; border-collapse: collapse;"> <tr><td>Doc/Data</td><td>☐</td><td>Unset/setup</td><td>☐</td></tr> <tr><td>Equip/Tooling</td><td>☐</td><td>Supplier</td><td>☐</td></tr> <tr><td>Handling/Pre</td><td>☐</td><td>Training</td><td>☐</td></tr> <tr><td>Material</td><td>☐</td><td>Use for Testing</td><td>☐</td></tr> <tr><td>Internal Transport</td><td>☐</td><td>Poor Information</td><td>☐</td></tr> <tr><td>Tribal Knowledge</td><td>☐</td><td>Rushing</td><td>☐</td></tr> <tr><td>LOA</td><td>☐</td><td>Product Improve</td><td>☐</td></tr> <tr><td>Substation</td><td>☐</td><td>Process Improve</td><td>☐</td></tr> <tr><td>Past Expiry Date</td><td>☐</td><td>Manufacturing Process</td><td>☐</td></tr> <tr><td>Misidentified</td><td>☐</td><td>Past Due</td><td>☐</td></tr> </table>		Doc/Data	☐	Unset/setup	☐	Equip/Tooling	☐	Supplier	☐	Handling/Pre	☐	Training	☐	Material	☐	Use for Testing	☐	Internal Transport	☐	Poor Information	☐	Tribal Knowledge	☐	Rushing	☐	LOA	☐	Product Improve	☐	Substation	☐	Process Improve	☐	Past Expiry Date	☐	Manufacturing Process	☐	Misidentified	☐	Past Due	☐	<table style="width:100%; border-collapse: collapse;"> <tr><td rowspan="10" style="width:30%; vertical-align: top;">Inqualified</td><td>☐</td><td>Power Loss/Surge</td><td>☐</td><td>Positioned Wrong</td></tr> <tr><td>☐</td><td>Folio/Program</td><td>☐</td><td>Outside Dimensions</td></tr> <tr><td>☐</td><td>Grain</td><td>☐</td><td>Over/Under tolerance</td></tr> <tr><td>☐</td><td>Weld</td><td>☐</td><td>Part Incorrect</td></tr> <tr><td>☐</td><td>Wrong Stock Pulled</td><td>☐</td><td>Part Lost/Missing</td></tr> <tr><td>☐</td><td>Out of Sequence</td><td>☐</td><td>Part Moved</td></tr> <tr><td>☐</td><td>Off-set</td><td>☐</td><td>Drawing</td></tr> <tr><td>☐</td><td>Mislabeled</td><td>☐</td><td>Finish</td></tr> <tr><td>☐</td><td>Fit/Function</td><td>☐</td><td>Misread</td></tr> <tr><td>☐</td><td>Misaligned/off center</td><td>☐</td><td>Turning Sequence</td></tr> <tr><td rowspan="2" style="vertical-align: top;">Unclear</td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td></tr> </table>		Inqualified	☐	Power Loss/Surge	☐	Positioned Wrong	☐	Folio/Program	☐	Outside Dimensions	☐	Grain	☐	Over/Under tolerance	☐	Weld	☐	Part Incorrect	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐	Out of Sequence	☐	Part Moved	☐	Off-set	☐	Drawing	☐	Mislabeled	☐	Finish	☐	Fit/Function	☐	Misread	☐	Misaligned/off center	☐	Turning Sequence	Unclear								
Doc/Data	☐	Unset/setup	☐																																																																																										
Equip/Tooling	☐	Supplier	☐																																																																																										
Handling/Pre	☐	Training	☐																																																																																										
Material	☐	Use for Testing	☐																																																																																										
Internal Transport	☐	Poor Information	☐																																																																																										
Tribal Knowledge	☐	Rushing	☐																																																																																										
LOA	☐	Product Improve	☐																																																																																										
Substation	☐	Process Improve	☐																																																																																										
Past Expiry Date	☐	Manufacturing Process	☐																																																																																										
Misidentified	☐	Past Due	☐																																																																																										
Inqualified	☐	Power Loss/Surge	☐	Positioned Wrong																																																																																									
	☐	Folio/Program	☐	Outside Dimensions																																																																																									
	☐	Grain	☐	Over/Under tolerance																																																																																									
	☐	Weld	☐	Part Incorrect																																																																																									
	☐	Wrong Stock Pulled	☐	Part Lost/Missing																																																																																									
	☐	Out of Sequence	☐	Part Moved																																																																																									
	☐	Off-set	☐	Drawing																																																																																									
	☐	Mislabeled	☐	Finish																																																																																									
	☐	Fit/Function	☐	Misread																																																																																									
	☐	Misaligned/off center	☐	Turning Sequence																																																																																									
Unclear																																																																																													
OTHER : _____																																																																																													